

From: **Vetting** <vetting@safe-ships.sg>
Date: Fri, Oct 14, 2022 at 5:03 PM
Subject: Re: Fwd: Vsl nom: Sindre Knutsen, Ardmore Seahawk, Atlantic Infinity
To: Sharon Tan <sharontan@pseraya.com.sg>
Cc: SystemOps <systemops@pseraya.com.sg>, Othman <othman@pseraya.com.sg>

Dear Sharon,

Please see below vetting results for the subject vessels.

Sindre Knutsen
Vessel cannot be cleared as her LOA of 277.55m exceeded Jetty 1 maximum LOA acceptance criteria of 275m.

Ardmore Seahawk
Vessel is suitable for Jetty 1 & 2.
There will be tidal restrictions for her berthing/unberthing at Jetty 1 & 2 if her draft exceeds 11.4m and 11.1m respectively.
Vessel's ballast freeboard including the manifold height is within Jetty 1 & 2 GO MLAs working envelopes.

Atlantic Infinity
Vessel is suitable for Jetty 1 & 2.
There will be tidal restrictions for her berthing/unberthing at Jetty 1 & 2 if her draft exceeds 11.4m and 11.1m respectively.
Vessel's ballast freeboard including the manifold height is within Jetty 1 & 2 GO MLAs working envelopes.

Best regards,
John

On 2022-10-14 15:01, Sharon Tan wrote:

Dear John,

Please help to clear above mentioned vessels for gasoil ops at PSPS. Thank you.

Regards,

Sharon Tan
System Operations

PetroSeraya Pte. Ltd (UEN 200705392E)

450 Alexandra Road #01-01

Singapore 119960

DID +(65) 6213 8636

Mobile +(65) 97929556

Web ytlpowerseraya.com.sg